

# PORTLAND SLIP WATERS EDGE PROMENADE

Central Waterfront Community Update Meeting  
2011.06.09

**WEST 8**

+

DTAH



# ONE WATERFRONT: COMPLETING THE VISION



# ONE WATERFRONT: COMPLETING THE VISION

Canada  
Malting Silos  
1928



Victory Soya  
Mills Silos  
1943



Portland Slip




York Slip



Parliament Slip

# ONE WATERFRONT: COMPLETING THE VISION



City of Toronto is currently undertaking substantial dockwall reconstruction work to replace an existing structure that has reached the end of its life.



# EXISTING CONDITION



# PHASING: DOCKWALL CONSTRUCTION





# PHASING: PROMENADE CONSTRUCTION



# TREE PLANTING

## Tree Spacing

Match East Bayfront promenade

## Silva Cells

Promenade trees supported by Silva Cells



# PHASING: EXISTING CONDITION



# CURRENT PHASE



# ONE WATERFRONT: COMPLETING THE VISION



## BEFORE




## CURRENT SITE STATUS





New dockwall sheet piling installed.

### Lake Ontario







Installation of anchor blocks.



New dockwall sheet piling installed.

# PHASING: PROMENADE CONSTRUCTION

